### **Nearly Easter**

25/3/2014 0 Comments

Well my last post was before Christmas so thought I would put digit to keyboard. Its nearly Easter and suffice it to say we have been flat out with all sorts of projects since the New Year, work has been nationwide from Cumbria to London and South East and down into the South West. We have purchased a new Leica TS15 imaging robotic total station, this kit has a calibrated camera and we are looking forward to using the images from this inside "ELCOVISION 10 for Leica Viva", we will let you know how we get on. This years rainfall has been challenging to say the least, many of our railway bridge surveys being postponed due to flooding, sometimes decisions about which site to go to have been made at 5:30am following a quick look at the EA gauging stations. As well as the storms disrupting work it has also generated some, with rail sites in Cumbria being as a direct result of damage to sea walls or track being left hanging along coastal routes.

We are all looking forward to some drier weather



Hole in sea wall filled with rock armour



Temporary rock armour protects a length of railway having been recently reinstated after storms

#### 0 Comments

# Grantham Coates Surveys

Land - Engineering - Measured Building Surveyors





### **Archives**

March 2016
November 2015
October 2015
April 2015
March 2015
January 2015
September 2014
August 2014
June 2014
March 2014
December 2013
October 2013
August 2013
May 2013

February 2013 December 2012 November 2012 October 2012

March 2013

September 2012

July 2012 June 2012

May 2012

April 2012

March 2012

February 2012

January 2012 December 2011

November 2011

October 2011

September 2011

August 2011

## Categories

All
Building Surveys
Laser Scanning
Measured Building Surveys
News
Topographic Survey
Topographic Surveys

View my profile on LinkedIn

