15/2/2012

0 Comments

English Heritage Level 4 Building Survey

This week we have carried out a laser scan of a range of buildings in Mid Wales as part of a archaeological Level 4 building survey (English Heritage 2006). Deliverables to include, site layout, building elevations and sections as well as point cloud data. Please see below preliminary data prior to attaching hi-res true RGB photography.



Laser scan overview



Laser scan for archaeological Level 4 building survey (English Heritage 2006)



Leica C10 laser scanner used to survey the buildings



True RGB colours burnt onto the point cloud

Sea Defence Survey

As well as the archaeological survey we are also carrying out survey work along a sea wall in North Wales. The project is to enable the design of sea defences to an existing wall with railway embankment above.



Leica Smart Rover establishing Ordnance Survey National Grid and Datum for sea wall survey

0 Comments

Rail and River, Night and Day 1/2/2012

Last week saw us complete topographic surveys at 3 different site across North Yorkshire. Starting near Harrogate

on Friday with a 6 hour night time possession on a short stretch of railway track for line side drainage design works. Followed by a couple of days on the railway north of York, again for drainage design, and finishing at the end of the week with a water course scour protection survey south of Todmorden.





Scour protection survey to protect railway bridge

Upcoming work

Upcoming work for the next few weeks includes more railway drainage survey works, sea defence survey, archaeological laser scanning survey in mid Wales, laser scan of a bands stage set for video projection and topographic survey of a Cider factory for architectural development.

Grantham Coates Surveys

Land - Engineering - Measured **Building Surveyors**





Archives

March 2016 November 2015 October 2015 April 2015 March 2015 January 2015 September 2014 August 2014 June 2014 March 2014 December 2013 October 2013 August 2013 May 2013 March 2013 February 2013 December 2012 November 2012 October 2012 September 2012 July 2012 June 2012 May 2012 April 2012 March 2012 February 2012 January 2012 December 2011 November 2011 October 2011 September 2011

Categories

August 2011

Building Surveys Laser Scanning Measured Building Surveys News Topographic Survey Topographic Surveys

View my profile on LinkedIn

RSS Feed

0 Comments

0 Comments