

Recent Laserscanning projects

5/8/2013


0 Comments



Distribution centre

Thought I would add some recent laser scanning project images to the blog this month.

We have also been to Berwick on Tweed to carry out a scour protection survey of the Railway Viaduct involving water course survey out to the estuary for hydraulic modelling.



Public House laser scan survey



Warehouse survey



Semi-detached house, captures a good deal of the street scene also



Watercourse survey of the river Tweed, 250m wide with some big bridges. The boat crew is just below the bank.



A spectator!



Surveying the viaduct at low tide

0 Comments

Grantham Coates Surveys

Land - Engineering - Measured Building Surveyors



Archives

March 2016
November 2015
October 2015
April 2015
March 2015
January 2015
September 2014
August 2014
June 2014
March 2014
December 2013
October 2013
August 2013
May 2013
March 2013
February 2013
December 2012
November 2012
October 2012
September 2012
July 2012
June 2012
May 2012
April 2012
March 2012
February 2012
January 2012
December 2011
November 2011
October 2011
September 2011
August 2011

Categories

All
Building Surveys
Laser Scanning
Measured Building Surveys
News
Topographic Survey
Topographic Surveys

[View my profile on LinkedIn](#)

[RSS Feed](#)