


Recent Laser Scans

16/10/2012

0 Comments



Factory laser scan

Following a recent trip to Holland John has been processing approximately 90 scanworlds collected with a Leica 7000 Laser scanner. The scan data will be utilised to enable the final design of conveyor systems.



Barn laser scan

In addition to the factory laser scan we have also recently completed a measured building survey of a Herefordshire barn. Topographic survey, floor plans, elevations and sections were required by the architect to enable design of an art gallery.

0 Comments

Rain! Rain! Rain! and Laser Scan in Holland!

5/10/2012

0 Comments



Devils Bridge, River Lune at Kirkby Lonsdale in flood. not one of our survey sites!
3d model.

It seems the poor summer is extending into Autumn with rain crossing the country every other day if not more frequently. This has caused us some problems over the last week with two of our scour protection river sites subject to rapidly rising water levels. Managed to complete one this week with another on hold until dry weather (hopefully!) results in what would normally be knee deep levels. On the plus side we have been laser scanning a warehouse/factory in Holland to provide 2d floorplans and



Team Sky coming through Kirkby Lonsdale on the Tour Of Britain

0 Comments

Grantham Coates Surveys

Land - Engineering - Measured Building Surveyors



Archives

March 2016
November 2015
October 2015
April 2015
March 2015
January 2015
September 2014
August 2014
June 2014
March 2014
December 2013
October 2013
August 2013
May 2013
March 2013
February 2013
December 2012
November 2012
October 2012
September 2012
July 2012
June 2012
May 2012
April 2012
March 2012
February 2012
January 2012
December 2011
November 2011
October 2011
September 2011
August 2011

Categories

All
Building Surveys
Laser Scanning
Measured Building Surveys
News
Topographic Survey
Topographic Surveys

[View my profile on LinkedIn](#)

 [RSS Feed](#)